

How to Borrow This Idea



This document will serve as a guide on how to **improve safety by painting forklift tines**...it's easier than you think!

Instructions:

1. Clean the tips of forklift tines thoroughly with brakleen or mineral spirits to remove all grease/oil from the surface.
2. Mask off the forklift tines 6-8 inches back from the ends of the tines. It is important to not mask off too much or too little as that will take away from the overall effect.
3. Paint the tips of the forklift tines with bright orange or yellow safety paint.
4. Let the paint dry and remove the masking materials from the forklift tines.

Materials and Parts used:

- Masking material (ex: painting tape)
- Brightly colored orange or yellow safety paint



Questions? We can help!

[Lean Everyday Ideas and Storeroom Contact Information](#)